ECS Configuration C	Page 1 of		Pag	ge(s)				
1. Originator	2. Log Date:	3. CCR #:		4. Rev	5. Tel:	6	6. Rm #:	7. Dept.
Willard Selph	08/21/03	03-0585			301-925-0368	3	3109J	SE
8. CCR Title: Ship and Install new e0dip08 and n0dip07 Rimage units								
or contribution of the model from the model of the model								
9. Originator Signature/Date			10. C	lass	11. Type:	Type: 12. Need Date: 08/21/03		
Willard Selph /s/ 8/21/03			II		CCR			
13. Office Manager Signature/Date Carolyn Whitaker /s/ 8/21/03			14. Category of Change: Other			15. Priority: (If "Emergency" fill in Block 27). Emergency		
16. Documentation/Drawings Impacted (Review and submit checklist): Docs updated with Rimage/Win2K PSR			17. Schedule 18. CI(s) Affected:PDS Impact:					
19. Release Affected by this Change: N/A 20. Date due 08/25			to Customer: 21. Estimated Cost: None - Under 100K					
22. Source Reference: NCR (attach) Action Item Tech Ref. GSFC Other:								
23. Problem: (use additional Sheets if necessary) New Rimage unit were purchased to replace the older unit.								
24. Proposed Solution: (use additional sheets if necessary) Ship and install new Rimage unit at LPDAAC and NSIDC.								
25. Alternate Solution: (use additional sheets if necessary) None								
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) The media that is required for the older units are almost depleted, newer media has been purchased but is not compatible with the older drives.								
27. Justification for Emergency (If Block 15 is "Emergency"): The new Rimage units need to be installed as soon as possible due to lack of media that required for the older drive units. There is also a need to return the old units to the vendor due to maintenance contracts.								
28. Site(s) Affected: □E		⊠EDC □ □Other	GSFC [□LaRC	⊠NSIDC □SM	ис 🗆]AK □JP	L
29. Board Comments:				30. \	Work Assigned To	o: 3	31. CCR (Closed Date:
32. EDF/SCDV CCB Chair (Sign/Date): D	isposition: A	pproved	App/Co	m. Disapproved	Withd	Iraw Fwd/	ESDIS ERB
		Fv	vd/ECS					
33. M&O CCB Chair (Sign/I Pam Johnson /s/ 8/21/03	Date): D	isposition: A	proved	App/Cor	n. Disapproved	Withdi	raw Fwd/E	SDIS ERB
1 alli Jolilisoti /s/ 0/21/03		Fv	vd/ECS					
34. ECS CCB Chair (Sign/D	Pate): Dis	sposition: Ap	proved	App/Con	n. Disapproved	Withdi	raw Fwd/	ESDIS ERB
		Fwd/ESDIS						

CM01JA00 Revised 8/2/02 ECS/EDF/SCDV/M&O

ADDITIONAL SHEET

CCR #: Rev: Originator: Willard Selph

Telephone: 0368 Office:

Title of Change: Ship and Install new e0dip08 and n0dip07 Rimage units

For the configuration of the new hosts, the following procedures need to be completed.

NOTE: There is custom code which needs to be installed before using the new host. The custom code is compatible with the old Rimage software.

- 1. Install new host on network and configure with IP address. Create the same users, as before on the old host, which has permissions on the new host as well as the x0dig0x host.
- 2. Install and configure Interdrive COTS product using 914-TDA-247 document.
- 3. If you plan to re-install the new version of Rimage Software Suite, you will follow the prompts from the setup.exe file. NOTE: You have to install the software first on the local host. This is required to complete the setup. After you have completed the installation you may continue on to the next step.
- 4. Install the Data Producer software (SDK6_0_15.zip file). Unzip the file and run setup to install.
- 5. Install PSpatch zip file.

Shipping the old host back to the vendor:

- 1. Run PGP disk on the host. Terry Thompson at LPDAAC and Mark Scwhab at NSIDC should have this product.
- 2. Pack up the computer and the Rimage unit (without the carosel) and ship to the following:

LPDAAC e0dip07** ein11487 & 11516

RMA# R28950 800-553-8312 Option 1

Ship to: Rimage Corporation

7725 Washington Ave South Minneapolis, MN 55439

n0dip07 ein's are 13292 & 13291 - RMA# R28950 800-553-8312 Option 1

Ship to: Rimage Corporation

7725 Washington Ave South Minneapolis, MN 55439

CM01AJA00 Revised 8/2/02 ECS